


Asbestos Registry

Healthcare Facilities within the Prairie North Health Region

			
	Facility Name: Northland Pioneers Lodge		
	Location: 515 - 3rd Street		
	Meadow Lake, SK		
	Date: November 14, 2014		
	Contact Person: Lloyd Bullock, Director of Environmental Services		
	Telephone (306) 820-2582		
Email - lloyd.bullock@pnrha.ca			
Type of Asbestos Containing Material	Location	Characteristics	Accessibility
Sheet flooring	room 308B, Stairwell	40% Chrysotile, Square patterns with flowers	Medium, non friable, limited staff in area
Pipe fitting mud compound	Crawlspace throughout facility except for 30 feet back from all entrances	20% to 40% Chrysotile, on insulated piping	Low, non friable, restricted access
Pipe fitting mud compound	Basement water softener room	30% Chrysotile, large insulated pipe	Low, non friable, restricted access
Pipe fitting mud compound	Basement, south end	60% Chrysotile, on west wing supply line	Low, non friable, restricted access
Pipe fitting mud compound	Crawlspace west of generator room	20% Chrysolite, on insulated pipes	Low, non friable, restricted access